6314998 - BOSTIK GRIZZLY MONTAGE POWER TUBE 100 G IT



GRIZZLY MONTAGE POWER SUPER STRONG AND FAST CONSTRUCTION ADHESIVE WITH HIGH INITIAL TACK AND HIGH FINAL STRENGTH FOR INTERIOR USE



PRODUCT DESCRIPTION

Universal, super strong and fast construction adhesive for interior use, with high initial tack (500KG/M² in 10 seconds) and high final strength (60KG/CM² in 24 hours). For bonding all kinds of objects onto porous surfaces.

FIELD OF APPLICATION

Suitable for all kinds of materials: e.g. wood, Trespa®, iron, aluminum, zinc, (stainless) steel, and other metals, stone, ceramic, concrete, brick, plaster, glass, PVC, ABS, PC, PMMA and other synthetic materials (test in advance), cork and polystyrene foam on porous surfaces like wood, stone, concrete, plaster and chipboard. To all kinds of objects: e.g. skirting boards, laths, window sills, tear plates, thresholds, fascia boards, plate material, insulation material, stair steps, sheeting material, floorboards, plasterboard, ceramic tiles and polystyrene ornaments and borders.

Not suitable for PE, PP, PTFE, bitumen, permanently moist places and for attaching a non-porous material on a non-porous substrate. When gluing plastics always perform an adhesion test first. Adhesion to plastics can vary depending on the type of synthetic and the quality of the plastic.

PROPERTIES

- · High initial tack (500KG/M² in 10 seconds)
- · High final strength (60KG/CM² in 24 hours)
- · For all materials
- \cdot Suitable for porous and uneven surfaces
- · For interior use
- Easy to apply
- · Filling
- Solvent-free

- · Permanently elastic
- Correctable
- Moisture resistant
- · Temperature resistant

PREPARATION

Working Conditions: Only apply at temperatures between $+5^{\circ}$ C and $+40^{\circ}$ C.

Surface Requirements: Both parts must be dry, clean and free of dust and grease. One of the two parts must be porous (absorbent).

Tools: Use putty knife or spatula to apply. If necessary, use a rubber mallet to tap lightly.

APPLICATION

Directions for use:

Before using, pierce the tube membrane with the puncture point integrated into the cap.

Apply one sided on a sturdy, clean and dust- and grease free surface. Apply in dots or stripes (10-40 cm). Firmly press or tap and leave to harden. Support heavy materials for 10 seconds. Remove excess adhesive immediately with ammonia. Final strength after 24 hours depending on surface and conditions. **Stains/residue:** Use water for cleaning tools and removing wet adhesive residue. Dry adhesive residue can only be removed mechanically.

TECHNICAL SPECIFICATIONS

Acrylic dispersion
Good
Cream
1.28 g/cm ³
10 sec for initial tack
Good
Good
24 hours
-20 °C
80 °C
Good
Very good
65 %
Very good
Pasty
Limited

* Curing time may vary depending on a.o. surface, product quantity used, humidity level and ambient temperature.

Our advice is based on extensive research and practical experience. However, in view of the large variety of materials and the conditions under which our products are applied, we assume no responsibility for the results obtained and/or any damage caused by the use of the product. Nevertheless, our Service Department is always at your disposal for any advice needed.

6314998 - BOSTIK GRIZZLY MONTAGE POWER TUBE 100 G IT



GRIZZLY MONTAGE POWER SUPER STRONG AND FAST CONSTRUCTION ADHESIVE WITH HIGH INITIAL TACK AND HIGH FINAL STRENGTH FOR INTERIOR USE

STORAGE CONDITIONS

Close container properly and store in a dry, cool and frost-freeplace.

Our advice is based on extensive research and practical experience. However, in view of the large variety of materials and the conditions under which our products are applied, we assume no responsibility for the results obtained and/or any damage caused by the use of the product. Nevertheless, our Service Department is always at your disposal for any advice needed.